(PROGRAMMABLE DC & AC SIGNAL ISOLATED TRANSMITTER)





■FEATURES

- •Accuracy 0.1%F.S.
- •Field-rangeable switchable DC/AC input ranges from 10mV to 600V/200uA to 5A, wide switchable DC output ranges over 20 standard process signal
- •Dielectric strength 2KVac/1 min.(input/output/power)
- •Wide input range for auxiliary power
- •Dimension small & High stability

$1.MODEL:TDP$ - \square	_ -						
	1 1 <u>1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 </u>						٦
√	<u> </u>	¥	→	\	\	\	\
NO Input Type NO Input Ra		NO Input Range	NO Input Range	NO Exciting Voltage	NO Output Range	NO Output Range	NO Aux.Power
A AC 10 0~10m\	20 1~5V	30 0~200uA	40 0~50mA	A 2.5V(<25mA)	A 0~0.5V	J 0~1mA	A AC/DC 18~60V
D DC 11 0~20m\	21 -5~+5V	31 0~500uA	41 10~50mA	B 5V (<50mA)	B 0~1V	K 0~2mA	B AC/DC 90~260V
12 0~50m\	[22] 0~10V	32 0~1mA	42 20~4mA	C 10V (<50mA)	C 0~2V	L 0~5mA	Less 3VA for
13 0~100m	/ 23 2~10V	33 0~2mA	43 50~10mA	D 12V (<50mA)	D 0~4V	M 1~5mA	AC/DC input
14 0~200m		34 0~5mA	44 0~0.5A	E 24V (<25mA)	E 0~5V	N 0~10mA	AC input frequency
15 0~500m	/ 25 0~20V	35 1~5mA	45 0~5A	N None	F 1~5V	O 0~16mA	(45~65Hz)
16 0~1V	26 0~100V	36 0~10mA	49 SPECIFIED	O SPECIFIED	G 0~8V	P 0~20mA]
17 -1~+1V	27 0~200V	37 2~10mA	●20~4mA & 50~10mA be	●DC0.5A/5A and	H 0~10V	Q 4~20mA]
18 0~2V	28 0~300V	38 0~20mA	reversed of input	AC input	I 2~10V	R SPECIFIED]
19 0~5V	29 0~600V	39 4~20mA	connection	non-exciting voltage			

2.SPCIFICATION

• Measuring accuracy : 0.1% F.S. (DC)($23\pm5^{\circ}$ C)

0.25% F.S. (AC RMS)

• Input resistance : >100 Mohm (<2V range) >1 Mohm (>2V range)

> >3 Mohm (>200V range) <10 ohm (uA/mA range) <0.01 ohm (A range)

• Maximum input : <1000V(>200V ranges)

> <150V(<2V ranges) <150mA (uA/mA ranges) <10A (A ranges)

Response time : <250ms (0~90%)

: <10mA for voltage mode <10V for current mode Output drive capability

: <0.1% F.S. • Output ripple(p-p)

• Construction

0~±165% F.S.(DIP-switches) 0~±5% F.S.(VR adjustable) • Zero (offset) range

: 0~165% F.S.(DIP-switches) 0~±10% F.S.(VR adjustable) · Span (scale) range

• Temp. coefficient : 100ppm/°C (0~50°C)

 Isolation : Input/Output/Power/Case

• Insulation Resistance :>100M ohm with 500V DC

• Dielectric strength : 2KVac/1 min. (input/output/power)

1600Vdc (input/output)

 Operating condition : 0~60°C (20 to 90% RH non-condensed)


· Storage condition : $0\sim70^{\circ}$ C (20 to 90% RH non-condensed)

• CE EMC Certification : EN 55022:1998/A1:2000 Class A


: Socket/plugin type with barrier terminals

EN 61000-3-3:1995/A1:2001 EN 55024:1998/A1:2001


3.TERMINAL CONNECTION




4.DIMENSION(unit:mm)



5.FUNCTION SWITCHES(S1,S2,S3,S4)




•S1 → P1-P2-P3-P4: input range selection P5: DC input selection(P5=ON,P6=OFF) P6: AC input selection(P5=OFF,P6=ON) P7-P8: DC input offset polarity selection



Effective input range " I "	S1 P1-P2-P3-P4	Program G
600V> I >200V	0 - 0 - 1 - 1	0.01/3
200V> I >20V	1 - 0 - 1 - 1	0.01
20V> I >2V	1 - 0 - 0 - 1	0.1
2V> I >200mV	1 - 0 - 0 - 0	1
200mV> I >20mV	1 - 1 - 0 - 1	10
20mV> I >2mV	1 - 1 - 0 - 0	100
5A> I >0.5A	1 - 1 - 0 - 1	10
0.5A> I >0.05A	1 - 1 - 0 - 0	100
50mA> I >5mA	1 - 1 - 1 - 1	1
5mA> I >500uA	1 - 1 - 0 - 1	10
500uA > I >50uA	1 - 1 - 0 - 0	100

•S2 → input range span (GAIN) selection

Span setting % -S2



•S3 → input range offset (ZERO) selection

Offset setting % -S3

N	<u>%</u>	1	2	4	8	10	20	40	80	ON
Р		1	2	3	4	5	6	7	8	
Status							=ena			OFF
			oles				:165%	6		
	All poles on				N=	:0%				

•S4 → P1-P2-P3-P4-P5-P6: output range selection P7-P8: output mode of voltage or current selection (Refer. output switching table)

6.PROGRAMMING FORMULA

VH/VL. AH/AL:input high/input low: G: program

VIII VE, AIII/AE.IIIpat IIIgiiiiipat	ion, o. program		
Voltage mode unit : volt	Current mode unit : mA		
•Span → X={10/[Gx(VH-VL)]}%	•Span →X={500/[Gx(AH-AL)]}%		
•Offset →Y=(100xGxVL)%	•Offset →Y=(2GxAL)%		

Note:1.Range selection: IVH-VLI should be > 0.1

IVHI...limited of program & range selection

2.Solution of non-linear problem: at input span IVH-VLI

< 0.2 IVHI, at normal setting switch calibration, if
non-linear happened, shifting offset switches up or down 1-2%, recalibrating to obtain correct output.

7.INPUT SWITCHING TABLE(S1,S2,S3)

(switching status 1=on; 0=off; X=don't care)

(switching status 1-on , 0-on , x-dont care)						
Input range	S3(ZERO)	S2(SPAN)	S ₁			
	1-2-3-4-5-6-7-8	1-2-3-4-5-6-7-8	1-2-3-4-7-8			
0~10mV	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-1-0-0-X-X			
0~20mV	1-1-1-1-1-1	0-1-0-1-1-1-1	1-1-0-0-X-X			
0~50mV	1-1-1-1-1-1	1-1-1-1-0-1-1	1-1-0-1-X-X			
0~100mV	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-1-0-1-X-X			
0~200mV	1-1-1-1-1-1	0-1-0-1-1-1-1	1-1-0-1-X-X			
0~500mV	1-1-1-1-1-1	1-1-1-1-1-0-1-1	1-0-0-0-X-X			
0~1V	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-0-0-0-X-X			
-1~+1V	1-1-1-1-1-0-1-0	0-1-0-1-1-1-1	1-0-0-0-1-0			
0~2V	1-1-1-1-1-1	0-1-0-1-1-1-1	1-0-0-0-X-X			
0~5V	1-1-1-1-1-1	1-1-1-1-1-0-1-1	1-0-0-1-X-X			
1~5V	1-1-1-1-0-1-1-1	0-1-0-1-1-0-1-1	1-0-0-1-0-1			
-5~+5V	1-1-1-1-0-1-0-1	1-1-1-1-0-1-1-1	1-0-0-1-1-0			
0~10V	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-0-0-1-X-X			
2~10V	1-1-1-1-1-0-1-1	0-0-1-1-0-1-1-1	1-0-0-1-0-1			
-10~+10V	1-1-1-1-1-0-1-0	0-1-0-1-1-1-1	1-0-0-1-1-0			
0~20V	1-1-1-1-1-1	0-1-0-1-1-1-1	1-0-0-1-X-X			
0~50V	1-1-1-1-1-1	1-1-1-1-1-0-1-1	1-0-1-1-X-X			
0~100V	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-0-1-1-X-X			
0~200V	1-1-1-1-1-1	0-1-0-1-1-1-1	1-0-1-1-X-X			
0~300V	1-1-1-1-1-1	1-1-1-1-0-1-1-1	0-0-1-1-X-X			
0~600V	1-1-1-1-1-1	0-1-0-1-1-1-1	0-0-1-1-X-X			
0~0.2mA	1-1-1-1-1-1	0-1-0-1-1-0-1-1	1-1-0-0-X-X			
0~0.5mA	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-1-0-0-X-X			
0~1mA	1-1-1-1-1-1	1-1-1-1-0-1-0-1	1-1-0-1-X-X			
0~2mA	1-1-1-1-1-1	0-1-0-1-1-0-1-1	1-1-0-1-X-X			
0~5mA	1-1-1-1-1-1	1-1-1-1-0-1-1-1	1-1-0-1-X-X			
1~5mA	1-1-1-1-1-0-1-1	0-0-1-1-0-1-1-1	1-1-0-1-0-1			
0~10mA	1-1-1-1-1-1	1-1-1-1-0-1-0-1	1-1-1-1-X-X			
2~10mA	1-1-0-1-1-1-1	0-0-1-1-1-0-0-1	1-1-1-1-0-1			
0~20mA	1-1-1-1-1-1	0-1-0-1-1-0-1-1	1-1-1-1-X-X			
4~20mA	1-1-1-0-1-1-1	0-1-1-1-0-0-1-1	1-1-1-1-0-1			
10~50mA	1-1-1-1-0-1-1	0-0-1-1-0-1-1-1	1-1-1-1-0-1			
20~4mA	1-1-1-1-1-0-1	0-1-1-1-0-0-1-1	1-1-1-1-0			
50~10mA	1-1-1-1-1-0-1-0	0-0-1-1-0-1-1-1	1-1-1-1-0			
0~0.5A	1-1-1-1-1-1	1-0-1-1-1-1-1	1-1-0-1-X-X			
0~5A	1-1-1-1-1-1	1-0-1-1-1-1-1	1-1-1-1-X-X			

^{•20~4 &}amp; •50~10mA be reversed of input connection

8.OUTPUT SWITCHING TABLE(S4)

(switching status 1=on; 0=off)

Output range	1-2-3-4-5-6	7-8
0~0.5V	0-1-1-1-0	1-1
0~1V	1-0-1-1-1	1-1
0~2V	1-1-0-1-1-0	1-1
0~4V	1-1-1-0-1-0	1-1
0~5V	1-0-1-0-1-0	1-1
1~5V	1-1-1-0-1-1	1-1
0~6V	1-1-0-0-1-0	1-1
0~8V	1-1-1-1-0-0	1-1
0~10V	1-1-0-1-0-0	1-1
2~10V	1-1-1-1-0-1	1-1
0~1mA	0-1-1-1-0	0-0
0~2mA	1-0-1-1-1	0-0
0~5mA	0-1-0-1-1-0	0-0
1~5mA	1-1-0-1-1	0-0
0~10mA	1-0-1-0-1-0	0-0
2~10mA	1-1-1-0-1-1	0-0
0~16mA	1-1-1-1-0-0	0-0
0~20mA	1-1-0-1-0-0	0-0
4~20mA	1-1-1-1-0-1	0-0